

**BOEING AEROSPACE COMPANY**

A Division of The Boeing Company

P.O. Box 3999  
Seattle, Washington 98124-2499

RECEIVED

MAR 18 1985

WASTE MANAGEMENT BRANCH

March 13, 1985  
2-4101-RWD-119

U. S. Environmental Protection Agency  
Region X  
1200 Sixth Avenue  
Seattle, WA 98101

Attention: George Hofer  
Chief, RCRA Permits Section

Reference: Our letter 2-4101-RWD-098 Dated March 5, 1985 Regarding  
Past Releases of Hazardous Waste Constituents at Plant II.

Dear Mr. Hofer:

We have reviewed the Washington State Department of Ecology and Metro permit files for Plant II. Based on this data, a supplement to the Environmental Spill Log previously submitted has been prepared. This supplement is for the period prior to 1980.

The spill log for discharges to the Metro sewer includes only those conditions that resulted from known spills. Out of permit limits conditions that occurred as a result of unknown or normal operations are not included.

Please contact R. W. Dalin on 773-5711 if you have any questions.

Further correspondence regarding Plant II Part "B" application I. D. No. 41337130 should be addressed to the undersigned as follows:

M. A. Schultz - M.S. 89-02  
Boeing Aerospace Company  
P.O. Box 3999  
Seattle, WA 98124

Sincerely,

*M. A. Schultz*  
M. A. Schultz

RWD:rm

**BOEING**

SCL 05948

CTY0050851

SEA291308

## BOEING AEROSPACE COMPANY - ENVIRONMENTAL SPILL LOG

LOCATION: PLANT II

DATE			LOCATION		RECEIVING ENVIRONMENT		CONTROL AGENCY		MATERIAL SPILLED	LBS.	COMMENTS
7	27	66	2-31	Bldg.	Metro	sewer	Metro		Chrome/nitric acid	1500	Circulating pipe ruptured discharging process tank contents to Metro sump.
7-19-67	2-41	"			Metro	sewer	Metro		Chromic acid	25	Tank overflowed to Metro sump.
4-16-68	2-10	"			Metro	sewer	Metro		Chromic acid	not known	Tank overflowed to Metro sump.
1-16-69	2-10	"			Metro	sewer	Metro		Chromic acid	not known	Tank overflowed to collection sump - leaked to Metro sump.
3-19-69	2-41	"			Metro	sewer	Metro		Chromic acid	not known	Steam coil leak.
8 3 72	2-41	"			Storm	sewer	D.O.E.		Trichloroethylene	not known	Part fell into degreaser tank punching hole in the tank.
1 30 73	S. of 2-10 Bldg.				Storm	sewer	D.O.E.		Chromic acid	not known	Surplus process tank was stored outside. Rainwater washed residue to storm sewer. \$100 fine.
10 19 73	2-10 Bldg.				Metro	sewer	Metro		Chrome/sulfuric acid	not known	Process tank overflowed to Metro sump.

SCL 05949

CTY0050852

SEA291309